HATON 03/10 77-A2/20 54-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Stan Hywet Hall, Carriage House and Garage 714 North Portage Path Akron Summit County Ohio HABS No. OH-50-A

Jack E. Boucher,	HABS Staff Photographer July 1982
OH-50-A-1	GENERAL VIEW OF CARRIAGE HOUSE FROM EAST
OH-50-A-2	CARRIAGE HOUSE, FROM WEST
OH-50-A-3	CARRIAGE HOUSE, FROM SOUTH
OH-50-A-4	VIEW SHOWING PASSAGE, WORK ROOM, AND WASH ROOM, FROM WEST
OH-50-A-5	DETAIL SHOWING PASSAGE, WEST SIDE, FROM SOUTHWEST
OH-50-A-6	VIEW OF PASSAGE, EAST SIDE
OH-50-A-7	VIEW OF GARAGE, SOUTH SIDE
OH-50-A-8	GARAGE, FROM SOUTHEAST

The following rectified photographs were taken by Chambers and Chambers Architects of Medina, Ohio in 1982(?). The captions include the Chambers and Chambers identification numbers and dimensions between the targets visible in each photograph. The camera positions are keyed to arrows indicated on the plans filed with the field records (see HABS No. OH-50).

			TARGET	DIMENSIONS
HABS No.	CAPTION	C & C No.	HORIZ.	VERT.
0H-50-A-9	STABLE/CARRIAGE ROOM, NORTH	CH-01	05'	none
OH-50-A-10	CARRIAGE ROOM, WEST	CH-02	24 '	none
OH-50-A-11	CARRIAGE ROOM, SOUTH	CH-03	10'	none
OH-50-A-12	PASSAGE/WORK ROOM/WASH ROOM	CH-04	18'9"	none
OH-50-A-13	OFFICE/PASSAGE, NORTH	CH-05	10'	none
OH-50-A-14	STABLE/PASSAGE, SOUTH	CH-06	10'	none

STAN HYWET, CARRIAGE HOUSE AND GARAGE INDEX TO PHOTOGRAPHS HABS No. OH-50-A (Page 2)

				TARGET DI	MENSIONS
HABS No.	CAPTION		C & C No.	HORIZ.	VERT.
OH-50-A-15	GARAGE,	SOUTH - LOWER TARGETS - UPPER TARGETS	Сн-08	20' 15'	5' none
OH-50-A-16	GARAGE,	SOUTHEAST END	СН-09	10'	none
OH-50-A-17	GARAGE,	VIEW FROM NORTHWEST	CH-11	unknown	
OH-50-A-18	STABLE,	VIEW FROM SOUTHEAST	CH-12	unkn	own

HABS OHIO, 77 - AKRO, 5-A-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

ADDENDUM TO STAN HYWET HALL, CARRIAGE HOUSE AND GARAGE 714 North Portage Path Akron Summit County Ohio HABS No. OH-50-A

OH-50-A-1 through OH-50-A-18 were previously transmitted to the Library of Congress.

INDEX TO COLOR TRANSPARENCIES

All color xeroxes were made from a duplicate color transparency.

Jack Boucher, Photographer, September 1977

OH-50-A-19 (CT) CARRIAGE HOUSE FROM WEST